

# SAFETY RECALL

## TORCOFIX / TORCOFLEX MOUNTZ TITAN and ERICO TORQUE WRENCHES

**The wrench's internal spring mechanism may fail or break, potentially causing bolts or screws fastened using the wrench to break or become unscrewed.**

Recalled wrenches include the following product/brand names and model numbers:

Product/Brand Name	Model Nos.
GEDORE/RAHSOL TORCOFIX K with Ratchet	4550-10; 4550-20; 4550-30; 4550-40
GEDORE/RAHSOL TORCOFLEX K with Ratchet	3550-07; 3550-10; 3550-20; 3550-30; 3550-2006
GEDORE/RAHSOL TORCOFIX Z with Spigot	4410-01; 4420-01; 4430-01; 4440-01
GEDORE/RAHSOL TORCOFIX SE with rectangle holder	4100-01; 4200-02; 4201-01; 4300-01; 4301-01
GEDORE/RAHSOL TORCOFIX K US with Ratchet	6550-15; 6551-07; 6551-10; 6551-30; 6551-60
MOUNTZ TITAN with Ratchet	280012; 280013; 280014
MOUNTZ TITAN with Spigot	280022; 280023; 280024
MOUNTZ ERICO ELT110D with Ratchet	ELT110D

Wrenches with the serial numbers within the following ranges are subject to the recall: **1268368 to 1341104; A003977 to A039760; B000493 to B032301; C000001 to C017795; E000001 to E020205; F000001 to F013249; H000001 to H000128; 2174340 to 2230753**

The serial number is indicated on the side of every torque wrench.

**Customers should immediately stop using these wrenches.**

The manufacturer will offer to repair or replace free of charge any recalled wrench.  
Customers are advised to send recalled wrenches to:

**KLANN Tools, Inc.**  
7187 Bryhawke Circle, Suite 700  
North Charleston, SC 29418

**Mountz, Inc.**  
19051 Underwood Road  
Foley, AL 36535

For more information about this recall contact KLANN Tools, Inc. at (866) 367-5526 or by email: [klanntools@knology.net](mailto:klanntools@knology.net)